



HASSELBLAD
CREATE TO INSPIRE

Distributed by Hasselblad Bron, Inc.
1080A Garden State Road, Union NJ 07083
1.800.456.0203
www.hasselbladbron.com

Hasselblad
Service &
Maintenance

Service & Maintenance Programs

V System - Check to Specification

Price: \$99.00

Program Description: All items are evaluated to ensure that they are operating at factory specifications
Includes four pieces: Body, Lens, Film Back and Prism
Additional pieces are inspected at \$36.50 per item
If a repair is needed, the \$99.00 inspection fee is waived and the customer will receive a 20% discount off the labor, parts not included.

*This offer is only valid for end-users

**Equipment must contain "Check-To Spec" Special Service Form that can be downloaded from the website by going to hasselbladbron.com Main Menu => Service and Support => Check-to-Spec - Hasselblad

V System Film Magazines - Clean, Lube, Adjust

Price: Labor charge \$150.00, includes replacement light traps and foil

Program Description: Disassemble, remove old lubricant, clean the internal components, apply new lubricant and install new light traps.

V System Bodies & Lenses - Clean, Lube, Adjust

Price: Typical labor charge is \$300.00

Program Description: Disassemble, remove old lubricant, clean the internal components, apply new lubricant, check the alignment for mirror/body and body length, evaluate the timing release sequence, ensure the lens is firing the flash, verify shutter speeds are correct, check optical integrity, confirm that the infinity focus is within the factory specifications, *calibrate prism meter, clean/lube lenses and ensure the film back is flat/true.

*some older meter prisms can't be calibrated due to age.

H System - Check to Specification

Price: \$159.00

Program Description: All items are evaluated to ensure that they are operating at factory specifications
Includes four pieces: Body, Lens, Prism, HM16-32 Film Back or Hasselblad Digital Magazine. Additional pieces are inspected at \$36.50 per item. If a repair is needed, the \$159.00 inspection fee is waived and the customer will receive a 20% discount off the labor, parts not included.

*This offer is only valid for end-users

**Equipment must contain "Check-To Spec" Special Service Form that can be downloaded from the website by going to hasselbladbron.com Main Menu => Service and Support => Check-to-Spec - Hasselblad

H System Bodies & Lenses - Clean, Lube, Adjust

Price: Labor charge \$145.00/hour plus spare parts

Program Description for H System: Perform system diagnostic, clean the internal components, apply new lubricant to the lenses, confirm flash synchronization, verify shutter speeds accuracy, confirm that the infinity focus for HC/HCD lens is within the factory specifications, calibrate prism meter, exterior cleaning of lenses, check the drive unit specifications for mirror/curtain for wear & tear, update firmware and validate the buttons responsiveness.

*Eye cups can also be replaced for \$59 (parts & labor) only the H System Models.

IR Filter External Cleanings

Price: Labor charge \$145.00; *plus spare parts if required*

Program Description: Digital magazine will receive a full diagnostic, firmware update, CCD alignment and UltraFocus calibration.

IR Filter Replacement

Prices (Labor & Parts):

\$750.00 - standard 16, 22, 31, 39 MP

\$675.00 - 40, 50, 60 (CCD) MP

\$725.00 - 50C, 200C (CMOS) MP

\$825.00 - 100C (CMOS) MP

\$895.00 - H2D22, 39(CCD) MP

*All H3D, H3DII, H4D, H5D, H6D require that both the body and digital back be sent in for a CCD alignment & UltraFocus calibration

**Please note that an additional firmware update charge of \$145.00 will also apply if applicable.

***H5D & H6D require repair at the corporate service center in Sweden

Linkboard Replacement (Firewire Port & CF Card)

Price (Labor & Parts):

\$987.00 - Linkboard replacement

Program Description: Linkboards are replaced. In addition, all items will receive a full diagnostic, firmware update, CCD alignment and UltraFocus calibration.

*All H3D, H3DII, H4D, H5D, H6D require that both the body and digital back be sent in for a CCD alignment and UltraFocus calibration.

**H5D & H6D require repair at the corporate service center in Sweden

Scanner Tune & Lube

Prices (Labor & Parts):

\$300.00 - Flextight 646, 848, 949, X1, X5

\$400.00 - Flextight 343

Replacement bulbs are an additional cost:

\$867.00 - X5

\$721.00 - 949

\$459.00 - 646, 848, X1

\$51.00 - 343

All items will be checked for any sign of physical damage, ensure the proper function of the power supply, replace the drive belts and springs (as necessary), lubricate drive screw, clean rollers (replace as necessary), clean optics/lens and inspect CCD (clean as necessary)

*All scanners, except for the Flextight 343 Scanners must include the original manufacturer's box, or no warranty will be provided on the work performed. Hasselblad Bron, Inc. does offer the sale of the scanner boxes at a cost of \$310 with high density foam inserts.

For more service information, please contact:

Hasselblad Bron, Inc.

Tel: 800-456-0203 - Option 2

Service: servicedept@hasselbladbron.com

Support: techsupport@hasselbladbron.com